From: Gary Moore

To: <u>Halasz, Stephen (Austin,TX-US)</u>

Subject: Falcon Refinery

Date: 02/13/2012 02:41 PM

Attachments: EPA weekly progress report 20120203.docx

## Stephen:

Thanks for the updated report. I have the following questions:

If I understand things correctly, the following are the remaining activities:

- 1. Tank 7,12, and 30: Internal roofs need to be removed so remaining liquid and sludge can be removed. If the tanks are going to be retained, the tanks will be inspected by API 653 to determine repairs needed. If the flooring is damaged (holes, cracks, etc.), such flooring will be removed and the contamination excavated and properly disposed.
- 2. Tank 26/Wasterwater Treatment: Wastewater Treatment System will be installed to treat the water from Tank 26 and irrigate it onsite. Upon completion of the treatment/irrigation activites, the remaining sludge within Tank 26 will be removed and disposed. Tank 26 will then be inspected by API 653 to determine repairs needed. If the flooring is damaged (holes, cracks, etc.), such flooring will be removed and the contamination excavated and properly disposed.
- 3. All piping and equipment throughout the facility will be completely drained of all materials and properly handled as product or waste as appropriate.
- 4. All visibly contaminated soils on the Falcon Refinery/NORCO property will be removed and disposed. The RI/FS will determine the fate of the non-visibly contaminated soils throughout the property.

Please let me know if there are other items that are being addressed that have not yet been completed.

On another note, I would like the following information provided to me:

- Copy of Watewater Treatment and Irrigation Plan
- Copy of the Analytical for the Raw Water that is going to be treated from Tank 26 (Full analytical should have already been done for designing the system). Does this water exhibit a hazardous waste characteristic or toxicity characteristic? If so, the LDRs may apply. Has this been checked out?
- It is my understanding that the refinery unit will be kept intact rather than demo for use by the new owner (all materials must be removed from all this piping and equipment as part of this removal). Also, any asbestos materials within the refinery unit and the whole facility should have already been removed during the early stages of the cleanup.

I will be calling Blue Dolphin shortly to discuss the above.

**Thanks** 



Gary Moore Federal On-Scene Coordinator EPA Region 6

Cell: 214-789-1627 Work: 214-665-6609

email: moore.gary@epa.gov

▼ "Halasz, Stephen (Austin,TX-US)" ---02/06/2012 01:15:58 PM---Gary, In last week's progress report in Section 1, I incorrectly indicated that the Purchaser of the

From: "Halasz, Stephen (Austin,TX-US)" <SHalasz@trcsolutions.com>

To: Gary Moore/R6/USEPA/US@EPA, Richard Bergner

<rbergner@rfblaw.net>
Date: 02/06/2012 01:15 PM

Subject: error

Gary,

In last week's progress report in Section 1, I incorrectly indicated that the Purchaser of the refinery is scheduling the removal of Tank 30. I meant to say that the Purchaser is scheduling the removal of the roof. I have included a corrected report.

Stephen Halasz Program Manager

505 East Huntland Drive, Suite 250, Austin TX 78750 T: 512.684.3351 | F: 512.329.8750 | C: 512.745.6155

Follow us on <u>LinkedIn</u> or <u>Twitter</u> | <u>www.trcsolutions.com</u>

\*\*\*\*\*\*\* ATTACHMENT NOT DELIVERED

\* \* \* \* \* \* \* \* \* \* \* \* \* \* \* \* \* \* \*

This Email message contained an attachment named image001.jpg

which may be a computer program. This attached computer program could

contain a computer virus which could cause harm to EPA's computers,

network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced

into the EPA network. EPA is deleting all computer program attachments sent from the Internet into the agency via Email.

bene from the internet fines the agency via haari.

If the message sender is known and the attachment was legitimate, you

should contact the sender and request that they rename the file name

extension and resend the Email with the renamed attachment. After

receiving the revised Email, containing the renamed attachment, you can

rename the file extension to its correct name.

For further information, please contact the EPA Call Center at (866) 411-4EPA (4372). The TDD number is (866) 489-

4900.



EPA\_weekly\_progress\_report\_20120203.docx